

RNP Aviation Services, LLC.
1969 Beechcraft 95-B55
N7700N, TC-1159
Logbooks – Right Propeller



MID FLORIDA AIRCRAFT PROPELLER, INC.

PROPELLER LOGBOOK

PROPELLER MODEL 2AF34C55-0/578FF-0

PROPELLER S/N 786395

LOGBOOK# _____



PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE

Propeller Model 2AF34C55-0

High/Feather _____

Propeller S/N 786395

Start Lock _____

Blade Design S78FF-0

Low _____

Blade S/N's

Reverse _____

No. 1 K92098 YS

No. 2 K99216 YS

Aircraft Manufacturer _____

No. 3 _____

Aircraft Model _____

No. 4 _____

S/N _____

No. 5 _____

Registration _____

No. 6 _____

Spinner Assembly Part No. _____

Date	Propeller		A Hr	atives, spections.
	TSN	TSO		
8/28/08		0		
<p>On August 28, 2008 Merlin fuelhauler propeller 2AF34C55-0/S78FF-0, S/N 786395, for McCauley Marine 71930, Barnica & SPM 100. Compliance with AD 68-10-03, AD 71-18-02, AD 92-14-04, SB, SIA, 88, 93, 93-1, 93-2, 93-3, 99, 99-1, 99-2, 99-3, 124A, 137AC, 183B & 184B. Returned to service this date, August 28, 2008. W/O 20154</p> <p style="text-align: right;"><i>Reed W. Wolfe</i> G2BR293X</p>				

MAINTENANCE RELEASE ISSUED

MID-FLORIDA AIRCRAFT PROPELLER, INC.
F.A.A. Approved Repair Station G2BR293X
4120 Roush Avenue
Orlando, Florida 32803

Date: 11/1/2008
AFTT: 6094.1


Aircraft: N7700N
S/N: TC1159

Hobbs: 1300.1
SMOH: 0.0

RIGHT PROPELLER

Installed Overhauled propeller in Right position on N7700N, AFTT 6094.1, Hobbs: 1366.1 Engine 10.3 SMOH.


I Certify this Propeller has been inspected I/A/W a ANNUAL inspection & was found to be in Airworthy condition at this time.



SHAUN PESKOR A&P2688662171A

RNP Aviation Services, LLC. 10062 Stanley Rd. Flushing, MI 48433 (810)444-3458	N 7700N	Tach/Hobbs:	1406.9 Hobbs	TTAF:	6134.9
	Logbook:	Right Propeller			
	TT (PROP):	----	(PROP) TSOH):	40.8	

I certify this PROPELLER has been inspected IAW a BEECH inspection guide and was determined to be in an AIRWORTHY CONDITION.


Joe J. Kruske

A&P3797450551A

12/01/2009

