

RNP Aviation Services, LLC.
1969 Beechcraft 95-B55
N7700N, TC-1159
Logbooks – Left Propeller



MID FLORIDA AIRCRAFT PROPELLER, INC.

PROPELLER LOGBOOK

PROPELLER MODEL 2 AF34C SSNO/78FF-0

PROPELLER S/N 700007

LOGBOOK# _____

①

PROPELLER MAINTENANCE RECORD

Position _____

Propeller Model 2AK34055NO

Propeller S/N 700007

Blade Design 78FF-G

Blade S/N's

No. 1 B1988245

No. 2 B2145845

No. 3 _____

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer _____

Aircraft Model _____

S/N _____

Registration _____

Propeller
TSN TSO

Hrs

Service Documents, Overhaul, Major or minor repair, and Inspections.

s Directives,

0

On July 8, 2008 Major overhauled propeller
3AF 3X55W0/T8FF-0, S/N 70007, per McCauley
Manual 710930, Bom 100 & SPmic. Complied with
AD 68-10-03, AD 71-18-02, SB 81A, 88, 93, 93-1, 93-2,
93-3, 99, 99-1, 99-2, 99-3, 124A, 137AC, 183B & 184B.
Returned to service this date, July 8, 2008.

W/O 2869A

W-2G

Rep 2732104

MID-FLORIDA AIRCRAFT PROPELLER, INC.

F.A.A. Approved Repair Station G2BR293X

4120 Roush Avenue

Orlando, Florida 32803

MAINTENANCE RELEASE ISSUED

Date: 11/7/2008
AFTT: 6094.1


Aircraft: N7700N
S/N: TC1159

Hobbs: 1366.1
SMOH: 0.0

LEFT PROPELLER

Installed Overhauled propeller in Left position on N7700N, AFTT 6094.1, Hobbs: 1366.1 Engine 10.3 SMOH.


I Certify this Propeller has been inspected I/A/W a ANNUAL inspection & was found to be in Airworthy condition at this time.



SHAUN PESKOR A&P2688662171A

RNP Aviation Services, LLC. 10062 Stanley Rd. Flushing, MI 48433 (810)444-3458	N 7700N	Tach/Hobbs:	1375.9 Hobbs	TTAF:	6103.9
	Logbook:	Propeller			
	TT LE/RE:	-----	SMOH LE/RE:	-----	
Removed Left Propeller for inspection by H&S Propeller, Inc. due to oil leakage. Reinstalled propeller after repair using new hardware. See Logbook Entry by H&S Propeller, Inc. dated 12/04/08 for more information on repair. Ground run and operational checks OK.					
Joe J. Kruske		A&P3797450551A	12/15/2008		

propeller
TSO

1. Approving National Aviation Authority / Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: S041473	
4. Organization Name and Address: H & S PROPELLER SHOP, INC. 6220 G - Row - Waterford, Michigan 48327				5. Work Order/Contract/ Invoice Number: W41473			
6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial / Batch Number:	12. Status / Work:	
ONE	PROPELLER	2A34C55-NO	N/A	ONE	700007	RESEAL	
13. Remarks: DISASSMBLED, CLEANED, INSPECTED, RESEALED, ASSMBLED AND BALANCED I/A/W McCAULEY MANUAL 710930. HUB S/N 700007.							
14. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 13.			19. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 13 Certifies that unless otherwise specified in block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.				
15. Authorized Signature:		16. Approval / Authorization No.:		20. Authorized Signature: 		21. Approval / Certificate No.: MQ5R050N	
17. Name (Typed or Printed):		18. Date (m/d/y): 00/00/00		22. Name (Typed or Printed): RICHARD M BANN JR.		23. Date (m/d/y): 12/10/2008	

RNP Aviation Services, LLC. 10062 Stanley Rd. Flushing, MI 48433 (810)444-3458	N 7700N	Tach/Hobbs:	1406.9 Hobbs	TTAF:	6134.9
	Logbook:	Left Propeller			
	TT (PROP):	-----	(PROP) TSOH):	40.8	

I certify this PROPELLER has been inspected IAW a BEECH inspection guide and was determined to be in an AIRWORTHY CONDITION.

Joe J. Kruske

A&P379745055IA

12/01/2009

RNP Aviation Services, LLC. 10062 Stanley Rd. Flushing, MI 48433 (810)444-3458	N 7700N	Tach/Hobbs:	1507.1 Hobbs	TTAF:	6235.1
	Logbook:	Left Propeller			
	TT (PROP):	-----	(PROP) TSOH):	141.0	

I certify this PROPELLER has been inspected IAW a BEECH inspection guide and was determined to be in an AIRWORTHY CONDITION.

Joe J. Kruske

A&P3506601IA

03/23/2011